

# Manhole Inspection Summary

Manhole # S21II\_016MH

Printed On: 6/10/2009

Page 1 of 3

**Inspection** ☒ **Is Incomplete** Rating:

Record Plat: **21II** Node: **016** Status: **Not Found**

Insp Date: **3/4/09 8:56 AM**

Incomplete Comments

**Cannot Access - Buried - Manhole Existing Confirmed by CCTV**

Crew: **ADS4**  
Inspector: **ADS4**  
Firm: **ADS**

**Location** Address: **1630 MCKEAN AVE**

Cross Street: **PRESBURY ST**

**Manhole** Type: Location: Ground Conditions:

☐ Prev. Rehab Weather: **Dry** Subject To Ponding: **None**

Comments **ATTEMPTED TO LOCATE IN ALLEY WITH METAL DETECTOR - NO RESULTS**

**Cover** Shape: Diameter: (in.) Length: (in.) Dist A/B Grade: (in.)

Type: **Sanitary** Condition: Cover Material: **Cast Iron**

Properties: ☐ Bolted ☐ Vented ☐ Water Tight ☐ Water Tight Insert

**Frame** Offset: (in.) Condition: ☐ Sound ☐ Cracked ☐ Leaks

**Chimney / Frame Adjustment** ☐ Exists Material: ☐ Parged Height: (in.)

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Corbel** Material: ☐ Parged Type:

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Barrel** Material: ☐ Parged

Shape: Diameter: (in.) Length: (in.)

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated

Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Bench** ☐ Exists Material: ☐ Parged

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

**Channel** Material: ☐ Parged

Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth:

Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

**Steps** Count: Missing: ☐ Corroded

**Surcharge** ☐ Evidence Of Surcharge Depth: (ft.) ☐ Active Surcharge Present



